

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection

B610633977

FACILITY: CLOVERLAND ELECTRIC COOPERATIVE - DETOUR		SRN / ID: B6106
LOCATION: 836 HIGHWAY M-134, DETOUR		DISTRICT: Upper Peninsula
CITY: DETOUR		COUNTY: CHIPPEWA
CONTACT: PHIL SCHMITIGAL , DIRECTOR OF GENERATION		ACTIVITY DATE: 03/29/2016
STAFF: Ed Lancaster	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: Conducted an unannounced, scheduled, compliance inspection.		
RESOLVED COMPLAINTS:		

The facility is located in Chippewa County, DeTour Village, on M-134.

The facility received an Opt-Out Permit (No. 193-09) on October 21, 2009 for two 3,000 kW diesel engine generators used for peak shaving and power outages. The units were installed in 1975 and are identified in the permit as EUENGINE6 and EUENGINE7.

The company submitted their 2015 MAERS on March 10, 2016.

When I arrived at the facility I introduced myself to Leslie, the Office Manager. She informed me the engines have not operated this year and for more detailed information about the engines I should talk to the Supervisor Mark Merchberger or Phil Schmitigal. Mr. Merchberger was in the field at the time of my inspection.


Based on a conversation I had with Mr. Schmitigal late last year and the company's recent MAERS submittal the units have not operated in over a year.

On April 15, 2016, I called Mr. Merchberger. He informed me both units need to be rebuilt before they can be operated again and the company is still considering its options for bringing the facility back on-line.

NAME



DATE



SUPERVISOR

