





4389 Lessing • Waterford, MI 48329  
(248) 623-0100 - office • (248) 623-3404 - fax  
www.paragonconcrete.net



August 4, 2015

Mr. Iranna Konanahalli  
Department of Environmental Quality  
27700 Donald Court  
Warren, MI 48092-2793



Dear Mr Konanahalli,

I have received your letter regarding the inspection. After our conversation we have purchased a dust collector system (Stephens Model :SOS-4000 ) which is currently being built (See P.O. attached). Delivery will be in 6-8 weeks. Installation should take approximately 2-4 weeks after delivery.

In the meantime we have constructed a temporary enclosure/ dust collection system (Photos included).

A safe, clean workplace is our number one goal here and we will continue our efforts to create that environment.

Sincerely,

A handwritten signature in black ink, appearing to read 'Mark Danhasuen'. The signature is fluid and cursive, with a long horizontal stroke at the end.

Mark Danhasuen