

DEPARTMENT OF ENVIRONMENTAL QUALITY

AIR QUALITY DIVISION

FCE Summary Report

Facility : Haworth Inc	SRN : B7186
Location : One Haworth Center One Haworth Center	District : Kalamazoo
	County : ALLEGAN
City : HOLLAND State: MI Zip Code : 49423	Compliance Status : Non Compliance
Source Class : MAJOR	Staff : Matthew Deskins
FCE Begin Date : 8/18/2016	FCE Completion Date : 8/18/2017
Comments :	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
08/18/2017	Scheduled Inspection	Non Compliance	Unannounced Scheduled Inspection
08/04/2017	MACT (Part 63)	Compliance	Subpart JJ (Wood Furniture) semi-annual Compliance Status Report. There are no HAPs in the coatings being used in the Laminated Product Plant.
08/04/2017	MACT (Part 63)	Compliance	Metal furniture NESHAP Compliance Status Report.
03/22/2017	MAERS	Compliance	
03/22/2017	ROP Annual Cert	Compliance	
03/22/2017	ROP SEMI 2 CERT	Compliance	The company forgot to assign a backup VE reader for premise panel dust collector during 2 weeks in July 2016. Now back in compliance.
03/22/2017	NSPS (Part 60)	Compliance	NSPS Subpart EE Report
02/09/2017	MACT (Part 63)	Compliance	Subpart JJ (Wood Furniture) semi-annual Compliance Status Report. There are no HAPs in the coatings being used in the Laminated Product Plant.
02/09/2017	MACT (Part 63)	Compliance	Subpart RRRR (Metal NESHAP) semi-annual compliance status report. This applies to FG-METALNESHAP. The monthly averages for lbs HAP per gallon applied solids were all less than 0.83, thus in compliance. The monthly averages were between 0.0017 and 0.0044.
09/29/2016	ROP Semi 1 Cert	Compliance	

Activity Date	Activity Type	Compliance Status	Comments
09/29/2016	NSPS (Part 60)	Compliance	NESHAPS Subpart EE Report

Name: Math Oak

Date: 8-31-17

Supervisor: MA8/31/2017