

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Scheduled Inspection

B913148837

FACILITY: BUCKEYE TERMINALS-JACKSON		SRN / ID: B9131
LOCATION: 2103 MORRILL RD, JACKSON		DISTRICT: Jackson
CITY: JACKSON		COUNTY: JACKSON
CONTACT: Lee Ann Beck , Specialist, HSSE Compliance		ACTIVITY DATE: 05/14/2019
STAFF: Stephanie Weems	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: Scheduled FCE Inspection.		
RESOLVED COMPLAINTS:		

### Full Compliance Evaluation (FCE) and Inspection of Buckeye Terminals LLC – Jackson (B9131)

#### Facility Contacts:

Facility Contact: Lee Ann Beck – Specialist, HSSE Compliance

Phone: 216-271-8203

Email: LBeck@buckeye.com

Website: <http://www.buckeye.com>

#### Purpose

On May 14, 2019 I conducted an unannounced compliance inspection of Buckeye Terminals LLC – Jackson located at 2103 Morrill Rd, Jackson, MI. The purpose of the inspection was to determine the facility's compliance status with the applicable federal and state air pollution regulations, particularly Michigan Act 451, Part 55, Air Pollution Control Act, and Permit to Install (PTI) 363-98.

#### Facility Location

The facility is located in Jackson County. It is adjacent to two other terminal facilities. See Image 1 for an aerial photo.

#### Facility Background

Buckeye Terminals is a gasoline storage facility. It has been idled/shutdown since 2011; however, the facility's management has chosen to keep its permit active pending any future decision to reopen.

The facility was last inspected on November 24, 2015, and it was reported idled at that time.

#### Regulatory Applicability

Buckeye Terminals was issued Opt-Out PTI 363-98 for this facility.

The facility submitted their annual MAERS report for 2018. They reported zero emissions due to the facility being idled.

#### Arrival & Facility Contact

I arrived at approximately 9:40AM.

No visible emissions or odors were observed upon my approach to the facility.

#### Onsite Inspection

The facility gate was locked, and no vehicles were seen near the office or on site (Image 2). The storage tanks exhibited rust on the tank exteriors (Image 3). There were signs on the outside of the gate indicating whom to call in case of emergency (Image 4). I departed the area at 9:45 AM.

#### Post-Inspection Correspondence

On May 14, 2019, I emailed Lee Ann Beck to inquire about the operations of the facility. The email

correspondence is attached with this report in the facility file.


Lee Ann informed me that the facility remains idle.

### **Compliance Summary**

Based upon the facility inspection and correspondence with Lee Ann, and due to its idled status, it is determined that the facility is in compliance at the time of this inspection.



**Image 1(1)** : Aerial view



**Image 2(2)** : Office



**Image 3(3)** : Storage tanks



**Image 4(4) :** Contact info sign.

NAME Steph W.

DATE 5.28.19

SUPERVISOR [Signature]