## DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

**ACTIVITY REPORT: Scheduled Inspection** 

F512643827		
FACILITY: ROBINSON INDUSTRIES INC		SRN / ID: F5126
LOCATION: 3051 CURTICE RD, COLEMAN		DISTRICT: Saginaw Bay
CITY: COLEMAN		COUNTY: MIDLAND
CONTACT:		ACTIVITY DATE: 03/16/2018
STAFF: Benjamin Witkopp	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Facility inspection	•	* .
RESOLVED COMPLAINTS:		

Ben Witkopp and Matt Karl of the Michigan Department of Environmental Quality - Air Quality Division (MDEQ-AQD) went to Robinson Industries at 3051 Curtice rd in Coleman. The facility is several miles north of US-10 and just west of M-18. We met with Mr. John Bradac. I had previously toured the operations in 2001, and the facility subsequently voided the permit (106-90) it had as the operations were deemed exempt from permitting.

Not much changed at the facility since the previous visit. The facility extrudes plastic into sheets and then uses vacuum thermoforming to produce the desired product. The facility primarily makes parts trays etc. for the automotive industry though it can make virtually anything with the proper mold. The facility does maintain a wood working / prototype shop for making molds.

The facility still has a wash sink (cold cleaner) and John was quick to point out the information I shared with him about proper operation back in 2001 was still posted by the unit.

The facility is considered in compliance and the operations witnessed at the time were indeed still exempt from permitting.

NAME 75. 245/1/3 DATE 7-19-18 SUPERVISOR C. Here