Page 1 of 2 <u>M4727</u>

MANILA

#### DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION ACTIVITY REPORT: Scheduled Inspection

M472737520

K ...

		0011100 111000
FACILITY: SPEEDWAY SUPERAMERICA LLC # 8737		SRN / ID: M4727
LOCATION: 27360 GRAND RIVER, REDFORD TWP		DISTRICT: Detroit
CITY: REDFORD TWP		COUNTY: WAYNE
CONTACT:		ACTIVITY DATE: 10/24/2016
STAFF: Jill Zimmerman	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: Verification that equip	ment has been removed.	
RESOLVED COMPLAINTS:		

DATE OF INSPECTION	2	October 24, 2016
TIME OF INSPECTION	:	2:30 pm
LEVEL OF INSPECTION	:	11
NAICS CODE		238290
EPA POLLUTANT CLASS	:	VOC
INSPECTED BY		Jill Zimmerman
PERSONNEL PRESENT	1	
FACILITY PHONE NUMBER	:	616-954-7015, ext. 226

# FACILITY BACKGROUND

The facility had operated an air stripper, soil vapor extraction systems, and air sparging systems, and the associated air pollution control devices at this gasoline filling station. The facility is located on the northeast corner of the intersection of Grand River Road and Inkster Road in Redford, Michigan.

#### COMPLAINT/COMPLIANCE HISTORY

No complaints have been received regarding this facility.

### **OUTSTANDING VNs**

No violations have been issued regarding this facility.

### PROCESS EQUIPMENT AND CONTROLS

The facility had been operating an unmanned air stripper, soil vapor extraction systems, and air sparging systems, and the associated air pollution control devices. Multiple pipes were extending from the ground.

### **INSPECTION NARRATIVE**

I arrived at the facility, which is a Sunoco Gas Station. I drove around the perimeter of the facility. There was no evidence of any remediation equipment at the facility. I looked along the building where the equipment had been located during my last inspection, and the equipment appears to have been removed.

A meeting involving Mr. Michael Cox as well as staff from the MDEQ-AQD from the Warren District Office has been set for Friday November 4, 2016 to discuss the multiple sites where the remediation equipment has been removed.

### APPLICABLE RULES/PERMIT CONDITIONS

The remediation equipment is operating under PTI 311-08, which was issued on September 29, 2008. There is one flexible group, which covered all of the remediation equipment.

On September 27, 2016 a letter was received from Speedway LLC requesting permit 311-08 be voided because the equipment has been removed. An attached letter from Mr. Michael Cox with Practical

Environmental Consultants, Inc. (PEC) stated that the remediation equipment had operated at this location between March 1, 2011 and August 24, 2016. This letter stated that the equipment had been removed from the site by October 7, 2016.

Based on the correspondence received from the facility as well as the visual inspection, it appears that the remediation equipment has been removed from this location. This general permit will be voided since it has been verified that this equipment has been removed.

MAERS REPORT REVIEW NA

## FINAL COMPLIANCE DETERMINATION

At this time, the facility has removed all of the permitted equipment from this location. Permit 311-08 will be voided.

fill Cymameric NAME\_

DATE 1/ 7/16\_ SUPERVISOR\_\_\_\_