STAFF REPORTMichigan Department of Environment, Great Lakes, and Energy

Hazardous Waste/Pt.111 Solid Waste/Pt.115	Liquid Ind.Waste/Pt.121 Scrap tire/Pt.169 Other		Corrective Action Sampling Inspection Telephone Call Meeting Notes Other		
Facility/Site Name Arbor Hills Landfill			Date/Time 10-5-2023 9:50pm – 11:00pm Facility/Site Number		
10699 W. Six Mile Road Participants/Contacts Anthony Testa			WDS 475946 Staff Gary Schwerin		
REFERRED TO:					
REMARKS (weather, unus	ual conditions, etc.): After receive	ving numerous odor complaints, I comple	ted an odor inspection around Arbor		
Hills Landfill. Temperatu	ıre was 61°, light sprinkles, ar	nd SSW wind at 6 mph. Times are ro	unded to nearest 5 minute.		
I completed inspections and made the noted observations at the following locations:					
Light (2) compost odor on 6-Mile adjacent to the compost area at 9:50pm					
50937 Briar Ridge Lane – No odor at 10:00pm					
18855 Bayberry Way – Very light (1) compost odor at 10:15pm					
18922 Heather Ridge Dr No odor at 10:20pm					
Strong (3) LFG odor on	6-Mile between Napier Rd ar	nd Crestbrook Dr. at 10:30pm			
Very Strong (4) LFG odor on Napier Rd. at NE corner of the landfill at 10:45pm					
	_				
	_				

DISTRIBUTION/CC:		
Signature	Dage	of