STAFF REPORTMichigan Department of Environment, Great Lakes, and Energy

Liquid Ind.Waste/Pt.121 Hazardous Waste/Pt.111 Scrap tire/Pt.169 Solid Waste/Pt.115 Other	Complaint Inspection Compliance Inspection Construction/Closure Inspection Permitting Inspection PEAS Investigation	Corrective Action Sampling Inspection Telephone Call Meeting Notes Other		
Facility/Site Name Arbor Hills Landfill		Date/Time 10-30-2023 9:35pm-11:10pm		
Address 10699 W. Six Mile Road		Facility/Site Number WDS 475946		
Participants/Contacts Anthony Testa		Staff Gary Schwerin		
REFERRED TO:				
REMARKS (weather, unusual conditions, etc.):				
REMARKS (weather, unusual conditions, etc.): After receiving numerous odor complaints, I completed an odor inspection				
near Arbor Hills Landfill. Temperature was 33 ⁰ , clear, and W wind at 4 mph. Time rounded to nearest 5 min.				
I completed inspections and made the noted observations at the following locations:				
Medium Intensity LFG odor (2.5) at Napier Road near the middle perimeter monitor at 9:40pm				
16340 Mulberry Way – Light (2) odor at 9:55pm				
16382 Mulberry Way – Light (2) odor at 9:55pm				
16500 Block of Mulberry Way – Light (2) odor at 10:05pm				
16243 Westminister Dr – No odor at 10:15pm				
17027 Boulder Dr – Light (1) LFG odor at 10:25pm				
17058 Boulder Dr – Light (1) LFG odor at 10:25pm				
49832 Parkside Dr – No odor at 10:35pm				
50232 Livingston Dr – No odor at 10:40pm				
16307 Westminister Dr – No odor at 10:50pm				
17290 Crestbrook Dr – No odor at 11:00pm				
Medium Intensity LFG odor (2.5) at Napier Road near the middle perimeter monitor at 11:10pm				

DISTRIBUTION/CC:		
Signature	Dage	of