STAFF REPORT

Michigan Department of Environment, Great Lakes, and Energy

Hazardous Waste/Pt.111 Solid Waste/Pt.115	Liquid Ind.Waste/Pt.121 Scrap tire/Pt.169 Other	 ☐ Complaint Inspection ☐ Compliance Inspection ☐ Construction/Closure Inspection ☐ Permitting Inspection ☐ PEAS Investigation 	Corrective Action Sampling Inspection Telephone Call Meeting Notes Other		
Facility/Site Name Arbor Hills Landfill			Date/Time 11-2-2023 6:40am to 7:40am		
Address 10699 W. Six Mile Road Participants/Contacts Anthony Testa			Facility/Site Number WDS 475946 Staff Gary Schwerin		
REFERRED TO:			Gary Guiweiii		
REMARKS (weather, unusual conditions, etc.): 36º, cloudy, wind SSW 4mph					
I visited the site this morning to see if the odor mitigating fan AHL was using to control odors was working. I could not see					
the fan and did not notice any masking scent (if they are using one). Filling was occurring near the west end of Cell 6					
along the south edge of the cell.					
There was a light (1) garbage odor at the NE corner of Napier and 6-Mile Road at 6:45am					
There were strong (3) garbage/LFG odors on 6-Mile between Napier and the entrance to the compost area between					
6:45am and 7:30am, downwind from the active filling area.					
There was a medium intensity (2.5) compost odor at 8660 Napier at 7:40am					
ll .					

DISTRIBUTION/CC:		
Signature	Dage	of