

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Scheduled Inspection

N278945450

FACILITY: Anscheutz Chevrolet		SRN / ID: N2789
LOCATION: 1074 US 23 North, ALPENA		DISTRICT: Gaylord
CITY: ALPENA		COUNTY: ALPENA
CONTACT:		ACTIVITY DATE: 08/01/2018
STAFF: Bill Rogers	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Scheduled minor source inspection		
RESOLVED COMPLAINTS:		

On August 1, 2018, I inspected a paint booth at Anscheutz Chevrolet in Alpena. This was an unannounced, scheduled minor source inspection.

The paint spray booth is located in the dealership's body shop, which is a separate building behind (to the east of) the main sales building. Mr. Brian Kash, the body shop manager, showed me the paint booth. It is a commercially manufactured, professional grade spray paint booth. It has air vents in the ceiling and in the floor. There were dry fabric filters in both sets of vents. They were new, and in good condition. Maintenance appeared to be good.

Estimating by eye, the two exhaust stacks for the booth appear to be perhaps 3 feet in diameter, discharging perhaps 25 feet above ground level. They had what looked like zero loss caps, discharging unobstructed vertically upward.

Mr. Kash showed me their paint use records for July. Some paint comes as quarts, other paint such as primers comes in gallons. They had used 77 quarts and 10 gallons in July, i.e. 39 gallons 1 quart in total. This is under the 200 gallons per month which would be allowed in an exempt paint operation, under the current exemption of Rule 287(c)(l).

It appears that under current rules this facility would not need a permit. However, as a permit was issued and the equipment is still in operation, the permit is still in effect.

NAME William J Rogers J. DATE 8/3/2018 SUPERVISOR SN