

STATE OF MICHIGAN

DEPARTMENT OF ENVIRONMENT, GREAT LAKES, AND ENERGY

LANSING



February 4, 2022

UPS NEXT DAY DELIVERY

Mr. Steven Pitsch Pitsch Companies 675 Richmond Street NW Grand Rapids, Michigan 49504

SRN/ID: N5619; Kent County

Dear Mr. Pitsch:

VIOLATION NOTICE

On January 28, 2021, the Department of Environment, Great Lakes, and Energy (EGLE), Air Quality Division (AQD) conducted an inspection at Pitsch Landfill located at 7905 Johnson Road, Belding, Kent County, Michigan.

the Code of Federal Regulations (40 CFR), Part 61, Subpart M (National Emission Standard for Asbestos), and Rule 942 of Part 55, Air Pollution Control of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended. The purpose of this inspection was to determine compliance with the requirements of Title 40 of

National Emission Standard for Asbestos (NESHAP) holds the owner and operator liable for all According to our investigation, Pitsch Companies is the owner and operator of the property. The violations.

During the investigation staff observed the following:

the Pitsch Landfill and all of them were manifested as friable asbestos. These loads of metal asbestos containing in Midland, Michigan. There were a total of 8 loads that were delivered to confirmed that this metal arrived at the landfill from a building that was being demolished as can be taken to the scrap yard. After looking at one of the waste shipment records, it was was in the process of being segregated. I was told that this metal was being segregated so it Located in the active part of the landfill, there was a large area with several piles of metal that were in the open and not covered.

VIOLATION NOTICE

Mr. Steven Pitsch Page 2 February 4, 2022

Process Description	Section Violated	Comments
Visible emissions from active waste disposal site where asbestos-containing waste material has been deposited.	40 CFR §61.154(a)	Visible emissions to the outside air from friable asbestos waste material not being covered within 24hr of disposal.
Failure to display warning signs.	40 CFR §61.154(b)	Failure to display warning asbestos warning signs at the entrance and every 330 ft along the property line.

Please initiate actions necessary to correct the cited violations and submit a written response to this violation notice by February 25, 2022 (which coincides with 21 calendar days from the date of this letter). The written response should include: the date(s) the violations occurred; an explanation of the causes and duration of the violations; whether the violations are ongoing; a summary of the actions that have been taken and are proposed to be taken to correct the violations, and the date(s) by which these actions will take place; and what steps are being taken to prevent a reoccurrence. The *signed* written response from the *owner and operator* to this violation notice, may be submitted by mail and directed to my attention at EGLE, AQD, P.O. Box 30260, Lansing, Michigan 48909-7760. You must also include a copy to Mr. Jason Wolf, Enforcement Unit at EGLE, AQD, P.O. Box 30260, Lansing, Michigan 48909-7760. The response may be scanned and emailed to BrownJ9@Michigan.gov and WolfJ2@Michigan.gov.

If you believe the above observations or statements are inaccurate or do not constitute a violation of the applicable legal requirements cited, please provide appropriate factual information to explain your position.

Thank you for your attention to resolving the violations cited above and for the cooperation extended to me during our conversation. If you have any questions regarding the violation notice or the actions necessary to bring this facility into compliance, please contact me at 517-599-7825; e-mail at BrownJ9@Michigan.gov; or the post office box address provided in the paragraph above.

Sincerely,

Jeremiah Brown

Senior Environmental Quality Analyst

Air Quality Division

cc: Ms. Mary Ann Dolehanty, EGLE

Dr. Eduardo Olaguer, EGLE

Mr. Christopher Ethridge, EGLE

Ms. Heidi Hollenbach, EGLE

Ms. Karen Kajiya-Mills, EGLE

Mr. Jason Wolf, EGLE