

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION

FCE Summary Report

Facility : Core Energy, LLC., Chester 10 CO2 Recovery	SRN : N5798
Location : SW 1/4 SW 1/4 SEC 10 T29N R2W	District : Cadillac
	County : OTSEGO
City : CHESTER TWP State: MI Zip Code : 49735	Compliance Status : Non Compliance
Source Class : SM OPT OUT	Staff : Shane Nixon
FCE Begin Date : 3/8/2016	FCE Completion Date : 3/8/2017
Comments : Emission limit violations and Rule 201 violation	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
02/22/2017	MAERS	Compliance	See MAERS For further info.
02/15/2017	Scheduled Inspection	Non Compliance	On site inspection and records review
01/23/2017	Malfunction Abatement Plan	Compliance	Malfunction Abatement Plan pursuant to PTI No. 579-95D. Staff review of the plan has determined it to be adequate.
03/22/2016	MAERS	Compliance	See MAERS database for further info.

Name: Shane Nixon Date: 3/8/17 Supervisor: _____