

DEPARTMENT OF ENVIRONMENTAL QUALITY

AIR QUALITY DIVISION

FCE Summary Report

Facility : Core Energy LLC - Chester 10 CO2 Recovery	SRN : N5798
Location : SW 1/4 SW 1/4 SEC 10 T29N R2W	District : Cadillac
	County : OTSEGO
City : CHESTER TWP State: MI Zip Code : 49735	Compliance Status : Compliance
Source Class : SM OPT OUT	Staff : Sharon LeBlanc
FCE Begin Date : 10/1/2022	FCE Completion Date : 10/12/2023
Comments : FY2024 FCE Report	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
10/12/2023	On-site Inspection	Compliance	2024 FCE site inspection and records review. sgl
03/23/2023	Other Non ROP	Compliance	Test Protocol for engine testing on Engine #3. Protocol submitted in a timely manner, appears complete, and was approved on 1/23/23. Testing took place on 2/7/23.
03/23/2023	Stack Test	Compliance	Test report for Engine 3, 2/13/23. See corresponding AR for review.
03/02/2023	MAERS	Compliance	See MAERS for more info.

Name: Sharon LeBlanc **Date:** 1-29-24

Supervisor: Shane Nixon