

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection

N605141064

FACILITY: O.I.L. ENERGY CORP. - Bagley 17 Facility		SRN / ID: N6051
LOCATION: 2646 DICKERSON RD, GAYLORD		DISTRICT: Gaylord
CITY: GAYLORD		COUNTY: OTSEGO
CONTACT:		ACTIVITY DATE: 08/14/2017
STAFF: Bill Rogers	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Scheduled inspection, minor source		
RESOLVED COMPLAINTS:		

On August 14, 2014, I inspected the O.I.L. Bagley 17 facility, off Dickerson Road near Gaylord. The facility is gone. I have marked it as such in the MACES database.

This facility was permitted. The permit was PI 602-96. The permit has already been voided.

There is no engine on site and no glycol dehydrator. There is a concrete slab where the compressor shed used to be. There are some disconnected pipe sections and fittings on the slab. There is a 400 barrel tank labeled "brine" inside a berm. The berm appears to be in poor condition. The tank is still piped to what appears to be wells, pipes disappearing underground in any case. There is also a second tank, smaller than the standard 400 barrel size, to the side outside of the berm. This tank does not appear to be attached to anything.

NAME William J Rogers, Jr

DATE 8/14/17 SUPERVISOR SN