

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION

FCE Summary Report

Facility : BREITBURN OPERATING LP - SHERMAN 35	SRN : N6060
Location : SW/4, NW/4, SW/4, T20N, R9W, SEC 35	District : Gaylord
	County : OSCEOLA
City : GILBOS CORNER State: MI Zip Code : 49688	Compliance Status : Compliance
Source Class : SM OPT OUT	Staff : Becky Radulski
FCE Begin Date : 3/17/19	FCE Completion Date : 3/17/2020
Comments : FY20 inspection and records review	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
03/17/2020	Other	Compliance	records review
03/04/2020	MAERS	Compliance	2019 MAERS, Check MAERS database for any review comments
02/26/2020	Scheduled Inspection	Compliance	FY20 scheduled inspection
01/22/2020	NSPS (Part 60)	Compliance	40 CFR 60 Subpart KKKK semiannual LDAR report. No leaks were detected for the reporting period
07/29/2019	NSPS (Part 60)	Compliance	40 CFR 60 Subpart KKKK semiannual LDAR report. No leaks were detected for the reporting period

Name: _____ **Date:** _____ **Supervisor:** _____