

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Scheduled Inspection

N612053671

FACILITY: BREITBURN OPERATING LP - PEGGY FLEMING		SRN / ID: N6120
LOCATION: SEC 5 T31N R4W NW, SW, SW, ELMIRA TWP		DISTRICT: Gaylord
CITY: ELMIRA TWP		COUNTY: OTSEGO
CONTACT: Eric Hasso , HSE Advisor I		ACTIVITY DATE: 05/20/2020
STAFF: Becky Radulski	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: FY2020 scheduled inspection		
RESOLVED COMPLAINTS:		

AQD Staff traveled to N6120 Breitburn Peggy Fleming Central Production Facility (CPF), located in Elmira Township, Otsego County, for a scheduled inspection to determine compliance with PTI 289-01A. This is an opt out permit.

### LOCATION

The facility is located in Elmira Township, Otsego County. From M-32, travel north on Camp Ten Road, turn west of Theisen Road. At the T in the road, turn north onto Webster Road and travel approximately 1 mile. The facility is on the east side of the road.

### REGULATORY DISCUSSION

PTI 289-01A was issued April 27, 2005 and is currently active. The permit was issued for one Caterpillar 399 TA, 830 hp compressor engine and a glycol dehydration system.

The engine is subject to 40 CFR Part 63, Subpart ZZZZ, which has not been delegated to MDEQ from EPA. The facility noted on the records that they are in compliance with Subpart ZZZZ regulations.

The glycol dehydrator is subject to 40 CFR Part 63, Subpart HH, which also has not been delegated to MDEQ from EPA. The facility noted on their records that they are in compliance with Subpart HH regulations.

### INSPECTION NOTES

The site consists of three buildings, surrounded by a fence with a locking gate. The gate was open during the inspection. Two buildings are associated with N7022 Riverside Thrive Warner (Thrive West, Warner 2). The third building, N6120 Breitburn Peggy Fleming, is the NW building. Only 1 of three buildings were operating during the inspection. The two westerly buildings, including Peggy Fleming, were not operating.

Discussions have taken place in previous reports on whether the three sources located on the same property should be reviewed as one ROP source. However emissions were reviewed in 2018 and determined to be well below ROP thresholds.

The Peggy Fleming CPF consists of a rich burn Caterpillar 399 engine with catalytic converter, glycol dehydration system and an iron sponge. Several drums were located onsite in containment, including engine oil and glycol dehydrator fluids.

As was mentioned earlier, the engine was not operating. Records provided by Breitburn show the most recent operating month being August of 2019. AQD Staff spoke with a Breitburn

operator at a different location (N6138 Saturday Night Live) who indicated the Peggy Fleming was offline with no known schedule to being processing gas again.

**COMPLIANCE DETERMINATION**

Based on the site inspection, N6120 Breitburn Peggy Flemming CPF is in compliance with the requirements of permit 289-01A.

Becky Radulski Digitally signed by Becky Radulski  
Date: 2020.06.05 09:23:58 -0400

Shane Nixon Digitally signed by Shane Nixon  
Date: 2020.06.05 09:24:57 -0400

NAME \_\_\_\_\_

DATE \_\_\_\_\_

SUPERVISOR \_\_\_\_\_