

DEPARTMENT OF ENVIRONMENTAL QUALITY
 AIR QUALITY DIVISION
ACTIVITY REPORT: On-site Inspection

N612660302

FACILITY: RIVERSIDE ENERGY MICHIGAN, LLC - CHARLTON WEST		SRN / ID: N6126
LOCATION: NW NW SEC 6 T29N R1W, CHARLTON TWP		DISTRICT: Gaylord
CITY: CHARLTON TWP		COUNTY: OTSEGO
CONTACT:		ACTIVITY DATE: 05/26/2021
STAFF: Becky Radulski	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: FY21 scheduled inspection		
RESOLVED COMPLAINTS:		

AQD Staff traveled to N6126 Breitburn Charlton West / Chain O Nine CPF for a FY21 scheduled inspection to determine compliance with PTI 684-96. This permit is a MOGA permit and an opt out.

The CPF is located in Otsego County, Charlton Township. The GPS coordinates uses in MAERS are incorrect and will be corrected. To locate the source from Gaylord, travel east on M-32 to Gingell Rd, turn south. Travel approximately 4 miles south, the facility is located on the west side of the road.

The site consists of a building with a Caterpillar engine with catalytic convertor which was operating during the inspection. No visible emissions or odors were noted. The engine oil pressure was 55 psi; catalytic inlet was 940 F, catalytic outlet was 1050 F. Several tanks containing hydraulic and engine oil were inside the building. Also onsite was a glycol dehydrator and lined tank berm with 1 tank which appeared to be less than 400 bbl.

The permit does not contain stack dimension requirements.

Based on the onsite observations, the facility appears to be in compliance with its permit.

NAME _____

DATE _____

SUPERVISOR _____