

DEPARTMENT OF ENVIRONMENTAL QUALITY
 AIR QUALITY DIVISION
 ACTIVITY REPORT: Scheduled Inspection

N620539458

FACILITY: Enervest, NORTH CHARLTON 31		SRN / ID: N6205
LOCATION: SE NE NW SEC 31 T31N R01W, CHARLTON TWP		DISTRICT: Gaylord
CITY: CHARLTON TWP		COUNTY: OTSEGO
CONTACT:		ACTIVITY DATE: 04/20/2017
STAFF: Gloria Torello	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: Site visit to assess request to void permit 30-87C.		
RESOLVED COMPLAINTS:		

The purpose of the site visit was to assess the permittee's request to void permit 30-87C.

There is an empty cement pad where the engine was located. The building housing the engine was removed. Also remaining are two large tanks in a lined retaining area,

With the engine removed, there is not an objection to voiding permit 30-87C.

NAME Gloria Torello DATE 4-21-17 SUPERVISOR SN