

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: On-site Inspection

N656272743

FACILITY: Saginaw Wilbert Vault Corp DBA North Central Mich		SRN / ID: N6562
LOCATION: 20702 M 115, MARION		DISTRICT: Cadillac
CITY: MARION		COUNTY: OSCEOLA
CONTACT: Mickey Brutsche , Owner		ACTIVITY DATE: 07/18/2024
STAFF: Tammie Puite	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Do a site visit to see if permitted equipment is still on site, and provide assistance if needed. Equipment is under new management.		
RESOLVED COMPLAINTS:		

FACILITY DESCRIPTION

I met with Michael Brutsche and Todd onsite to discuss the incinerator and what records need to be kept, and how to go about updating the permits. This facility is permitted to burn pathological waste.

This location is in the woods, just off M-115. There are 3 buildings onsite. The incinerator is in the Northwesterly brown building. When I was onsite, there were 2 units in the incinerator building. The permitted unit was installed; however the unit is not operating. There was a second unit, that is not installed, and was from a location in Hamilton. It was clear that work is being done to bring this business back online, however it is not currently in operation.

COMPLIANCE EVALUATION

This facility needs to keep records of: Type of Waste Burned – Pathological, Medical/ Infectious, and Type O; Average Temp in the Secondary Chamber, showing that it is at or higher than 1600 °F; Operating Times; Inspection Log; Maintenance Log; and Stack Observations during operating periods.

Information was provided as to what records need to be kept once up and operating, and how to update and get the new incinerator permitted for use.

SUMMARY

The last time this facility was inspected was in 2012. I didn't ask about previous operations, due to the business being under new management and not operating. I wanted to focus on the future, and ensure all requirements are being followed in the future. At this time, everything on site looked good.

NAME 

DATE 7-30-24SUPERVISOR 