DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

SRN: N6833 Facility: Wolverine Power, Gaylord Generating Station District: Gaylord Location: 2700 Millbocker Road County: **OTSEGO** Compliance City: State: MI Zip Code: 49735 Compliance **GAYLORD** Status: Staff: Becky Radulski Source Class: **MAJOR FCE Completion** 8/31/2015 FCE Begin Date: 8/31/14 Date: Comments: scheduled inspection and records review

List of Partial Compliance Evaluations:

Activity Date	Activity Type	Compliance Status	Comments
08/26/2015	Scheduled Inspection	Compliance	scheduled inspection and records review
03/31/2015	ROP Annual Cert	Compliance	Annual certification received on time and properly certified. No deviations.
03/31/2015	ROP SEMI 2 CERT	Compliance	semi annual report received on time and properly certified. no deviations.
03/09/2015	MAERS	Compliance	2014 MAERS, Check MAERS for any review comments
10/14/2014	Stack Test	Compliance	stack test results received and reviewed, Derenzo was tester. Emissions were lower than permitted limits on all three turbines.
09/16/2014	ROP Semi 1 Cert	Compliance	semi annual report received on time - no deviations reported.

Name: Bedar Radu Spate: 8

8/31/15

Supervisor:

Page 1 of 1