

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: On-site Inspection

N719474639

FACILITY: VCP Michigan - Canada Creek		SRN / ID: N7194
LOCATION: NE NW NE Sec 6, BRILEY TWP		DISTRICT: Cadillac
CITY: BRILEY TWP		COUNTY: MONTMORENCY
CONTACT:		ACTIVITY DATE: 10/30/2024
STAFF: Tammie Puite	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: 2025 FCE inspections for Minor source listed as operating under Exemptions.		
RESOLVED COMPLAINTS:		

On October 30, 2024 I arrived on site to find the CPF being well maintained per industry standards. Outside is a large separator, that has zero pressure. There are 3 AST tanks. Two tanks are inside secondary containment and one that is located behind the buildings in the grass. The two tanks inside the secondary containment appear to be the only thing that is operating onsite. These tanks are considered exempt.

Inside the building is a dehy unit with zero pressure. There is no engine, separators, scrubbers or piping inside the building.

I am removing this minor - exempt source off the AQD watch list, and closing the source.



Image 1(N7194 - Canada Creek) : CPF Building and 2 AST Tanks



Image 2(Interior View - 1) : No Engine or other equipment.




Image 3(Interior View -2) : Dehy Unit



Image 4(Interior View -3) : Engine Condenser but no engine or stack



Image 5(Separator) : No PSI

NAME 

DATE 12-4-24

SUPERVISOR 