

**DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: On-site Inspection**

N741264285

FACILITY: Carbon Green Bioenergy		SRN / ID: N7412
LOCATION: 7795 Saddlebag Lake Rd, LAKE ODESSA		DISTRICT: Grand Rapids
CITY: LAKE ODESSA		COUNTY: BARRY
CONTACT: Alec Rice , Manager		ACTIVITY DATE: 08/23/2022
STAFF: Eric Grinstern	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: On-site compliance inspection		
RESOLVED COMPLAINTS:		

**On-site inspection conducted at Woodbury Grain.**

Prior to entering the facility, a survey from off-site showed no fugitive emissions. The facility was not shipping or receiving grain at the time of the observations.

At the facility, staff (EG) met with Alec Rice, Manager.

The facility was issued a VN (November 19, 2020) for fugitive dust resulting from the loading and unloading of grain. The facility took action to reduce fugitive emissions in response to the VN. One complaint regarding fugitive emissions was received in November 2021. An investigation of the complaint did not document a violation.

Mr. Rice detailed the actions taken by the facility to address fugitive emissions.

1. Applied crushed asphalt to the facility roadways
2. Added mats to cover the loadout pits to reduce emissions during processing
3. Added powered tarps to the facility's two trucks
4. Added extensions to the load-out spout from the north storage building

Staff asked about the loadout spouts from the other silos. Mr. Rice stated that those spouts are for emergency use and are not for routine load-out.

The facility appears to be in compliance at this time, however, staff will continue to evaluate the facility for fugitive emissions during corn harvest.

NAME *Eric Grinstern*      DATE 8/25/2022      SUPERVISOR *[Signature]*