

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Scheduled Inspection

N773354775

FACILITY: MILESTONE MATERIALS INC		SRN / ID: N7733
LOCATION: PORTABLE CRUSHING PLANT, IRONWOOD		DISTRICT: Marquette
CITY: IRONWOOD		COUNTY: GOGEBIC
CONTACT: TARA WETZEL , ENVIRONMENTAL ENGINEER		ACTIVITY DATE: 08/26/2020
STAFF: Sydney Bruestle	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Records request to verify compliance with PTI 360-06 and all other applicable state and federal air quality regulations		
RESOLVED COMPLAINTS:		

On August 19, 2020 I sent a records request to Patrick Paulino, of Milestone Materials for the crushing plant when operated in Michigan in 2019 and 2020.

Below are the crushing records for the sites the plant operated in Michigan in 2019 and 2020:

1. Mottes Site (Section 15, T42N, R34W, Stambaugh Township, Iron County, 1829 County Road 424, Crystal Falls, MI 49920)

12/4/19 -1/29/20 and made the following:

- 22A Base: 11,756 ton
- 23A Base: 6,691 ton
- 7/16x1/4 Chip: 19,271 ton
- 1/4 Bit Gravel: 22,718 ton
- 5/8 Screened Sand: 46,869 ton

Total: 107,305 ton

2. Bergland Quarry (Section 7, T49N, R42W, Bergland Township, Ontonagon County, South of Forest Service Road 360 and M-64 intersection, Bergland, MI 49947)


6/9/20 - 6/25/20 and made the following:

- 22A Base: 12,136 ton
- 23A Base: 5,501 ton
- 6" minus breaker run: 4,461 ton

Total: 22,098 ton

NSPS testing is attached to the hard copy of this report. Testing was done 8/12/2012.

At the time of my records request, it appeared the facility is in compliance with PTI 360-06 and all other applicable state and federal air quality regulations.

NAME  DATE 9-9-20 SUPERVISOR 