

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection

N833736748

FACILITY: BRONCO OIL CO		SRN / ID: N8337
LOCATION: 1482 WEST M12, GAYLORD		DISTRICT: Gaylord
CITY: GAYLORD		COUNTY: OTSEGO
CONTACT:		ACTIVITY DATE: 09/16/2016
STAFF: Bill Rogers	COMPLIANCE STATUS: Compliance	SOURCE CLASS:
SUBJECT: Site check		
RESOLVED COMPLAINTS:		

I thought I had checked this facility in the past, but couldn't find my report. Now I have found it; I did in fact check it in 2013.

In any case, on September 16, 2016, I checked the gas station which was formerly Bronco Oil to see whether there was any trace of groundwater remediation equipment still in place. I checked the paved areas and enclosures on site; the suspicious-looking structure turned out to be a outdoor freezer for the fast food restaurant now on site. I found no evidence of groundwater remediation equipment at this location.

Review of Permit Cards indicate the permit for this location has already been voided.

NAME William J Rogers

DATE 9/23/16

SUPERVISOR 