

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection

P006929882

FACILITY: MDNRE RRD Cadillac District		SRN / ID: P0069
LOCATION: 207 W Grandview Parkway, TRAVERSE CITY		DISTRICT: Cadillac
CITY: TRAVERSE CITY		COUNTY: GRAND TRAVERSE
CONTACT:		ACTIVITY DATE: 06/10/2015
STAFF: Shane Nixon	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: on site inspection		
RESOLVED COMPLAINTS:		

AQD staff visited the site of the remediation process located at 207 West Grandview Parkway in Traverse City. Upon arrival, AQD staff noted the equipment was removed from the site. Ms. Ann Emington, MDEQ RRD, confirmed the removal. AQD staff will submit a request to Lansing to have the permit voided.

NAME Shane Nixon

DATE 6/23/15

SUPERVISOR 