DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

Facility: RIVERSIDE - SNOWPLOW CPF	SRN : P0148	
Location : SW 1/4 NW 1/4 SW 1/4 SEC 10 T29N R5E	District: Gaylord	
	County: ALPENA	
	npliance Compliance tus:	
Source Class: MINOR S	taff: Becky Radulski	
0 0/./=0	CE Completion 8/7/2024 ate :	
Comments: FY24 inspection and records review		

List of Partial Compliance Evaluations:

Activity Date	Activity Type	Compliance Status	Comments
08/07/2024	On-site Inspection	Compliance	inspection and records review
03/14/2024	Annual Emissions Report (or MAERS)	Compliance	Annual emissions were reviewed separately in MiEnviro. No issues were noted with the emission submittal, which was received on time.

Namecky Radubki Date: 11-8-24 Supervisor: Page 1 of 1