

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Self Initiated Inspection

P033837242

FACILITY: SPEEDWAY LLC STORE #8389		SRN / ID: P0338
LOCATION: 4019 N STATE RD, DAVISON		DISTRICT: Lansing
CITY: DAVISON		COUNTY: GENESEE
CONTACT: Ryan Sabol , Environmental		ACTIVITY DATE: 10/18/2016
STAFF: Nathaniel Hude	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Self Initiated inspection based on county file review and purging. Targeted due to having an older permit that generally uses temporary equipment.		
RESOLVED COMPLAINTS:		

**Inspection Report**

P0338- Speedway #8389  
4019 N. State Road  
Davison, MI 48423

**Inspection Date:**

10/18/16

**Facility Contacts:**

Ryan Sabol, Speedway LLC, 937-863-7667, [rtsabol@speedway.com](mailto:rtsabol@speedway.com)  
Jim Innes, MDEQ RRD, 517-284-5115, [innesj@michigan.gov](mailto:innesj@michigan.gov)

**MDEQ AQD Personnel:**

Nathan Hude – 517-284-6779, [huden@michigan.gov](mailto:huden@michigan.gov)

**Facility Description:**

This site was active Speedway. No ground water / soil remediation device was found on site. The location is on the NW corner of N State Road and E Richfield Road.

The DEQ Storage Tank Information Database websites provide the following information:

Facility ID: 00002369

LUST Site Name: CMS #22

Leak ID: C-1529-90, Discovery Date: 8/15/1990, Substance: no info, Release Status: Open

LUST Site Name: Speedway #8389

Leak ID: C-0168-12, Discovery Date: 12/14/2012, Substance: gasoline, Release Status: Open

Owner Information: Speedway LLC, PO Box 1500, Springfield, OH 45501, Phone#: (937) 864-3000

[http://www.deq.state.mi.us/sid-web/Tank\\_Detail.aspx?mod=lust&Site\\_ID=00002369](http://www.deq.state.mi.us/sid-web/Tank_Detail.aspx?mod=lust&Site_ID=00002369)

Permit Cards identifies the Company Contact as:

Speedway LLC, 500 Speedway Drive, Enon, OH 45323

**Applicable Regulations:**

PTI 58-12

**Previous Inspections:**

none

**Previous Violations:**

none

**Recent Complaints (within 2 years):**

none

**Number of Violations Found During this Inspection:**

none

**Inspection Key Concerns:**

none

**MAERS Reporting**

none

**MAERS Emission Unit List**

none

**Inspection Summary**

I stopped to inspect this site on 10/18/16. The site is an inactive Speedway gas station. I confirmed that no ground water / soil remediation device is on site after walking the property and speaking with the manager Kelley Fischer. She did show me that a manhole was recently installed on the east side of the building, but the purpose was unknown.

Due to the removal of the device, PTI 58-12 will be voided in accordance with General Condition 1.

The void notification letter will be sent to the following address:

Speedway LLC  
Attn: Ryan Sabol  
500 Speedway Drive  
Enon, OH 45323

A copy of this report will be used to void PTI 58-12 in accordance with MDEQ memo Procedure for Voiding Permits to Install, dated June 7, 1999.

Although the permit will be voided, this site will still have an "open" status in the RRD spill database until further action by the appropriate parties is completed. The RRD contact for this site is Jim Innes.

NAME 

DATE 10/24/16

SUPERVISOR: 