DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: On-site Inspection

P123473971			
FACILITY: TODD'S WELDING SERVICE, INC		SRN / ID: P1234	
LOCATION: 499 WOOD ROAD, RAPID CITY		DISTRICT: Cadillac	
CITY: RAPID CITY		COUNTY: KALKASKA	
CONTACT:		ACTIVITY DATE: 05/14/2024	
STAFF: Caryn Owens	<b>COMPLIANCE STATUS:</b> Compliance	SOURCE CLASS: MINOR	
SUBJECT: On Site Inspection			
RESOLVED COMPLAINTS:			

On Tuesday, May 14, 2024, I arrived on site at 9:45am and met with Brian the on-site contractor/wheel loader who was waiting for a Fishbeck to arrive on site before he began to operate the crushing operations. When Jacob Abir from Fishbeck arrived on site, I wanted the equipment clarified with the SRN number and mentioned that his SRN for what we were testing was the wrong one.

The crusher for P1234 is very large and has one conveyor off of it, and it is only used for Cushing concrete and limestone and big rocks, it is not used very often, and they did not have a water source for testing today so we'll be testing that crusher at a different time. I plan on following up with the source and inspecting this crusher in Fiscal Year 2025.

mens NAME

DATE 11-1-24

Ixon SUPERVISOR