

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Self Initiated Inspection

U25160358334190

FACILITY: Genesee Interm. School Dist- Gen. Career Institute		SRN / ID: U251603583
LOCATION: G-5081 Torrey Road		DISTRICT: Lansing
CITY: Flint		COUNTY: GENESEE
CONTACT: Karl Lang , Assistant Director of Operations		ACTIVITY DATE: 03/30/2016
STAFF: Nathaniel Hude	COMPLIANCE STATUS: Compliance	SOURCE CLASS:
SUBJECT: This inspection is part of the Genesee County Incinerator Permit compliance checks for the purpose of file clean-up and permit voidance where applicable.		
RESOLVED COMPLAINTS:		

Inspection Report

**U251603583- Genesee Career Institute (formerly Flint Board of Education- Skills Center Trade Bldg)
G-5081 Torrey Road
Flint, MI 48507**

Inspection Date:

March 30, 2016

Facility Contacts:Mr. Karl Lang- GISD Assistant Director of Operations, klang@geneseeisd.org

Mr. Dave Burt- GISD Director of Operations

MDEQ AQD Personnel:Nathan Hude – huden@michigan.gov, 517-284-6779**Facility Description:**

This building was once Flint Skills Center Trade Building for 11th and 12th grade trade instruction. The site is now known as Genesee Career Institute.

Applicable Regulations:

1. 115-681

Previous Inspections:

No documented inspections in files

Previous Violations:

None

Were past Violations corrected for this Inspections (if not list):

none

All Violations Found During this Inspection including reoccurring:

none

Recent Complaints (within 2 years):

none

Inspection Key Concerns:

none

MAERS Reporting

NA

MAERS Emission Unit List

NA

Inspection Summary

I entered the visitor entrance area where Brad Case let me in. I informed Brad of the purpose of my visit and provided him a copy of the Inspection Brochure and my business card. Brad escorted me to the mechanical room area and stated he would get Karl Lang who is the GISD Assistant Director of Operations to assist me. The building is in the process of being completely renovated with completion plans in or around 2018. When Karl arrived, I provided him with my business card and informed him of my purpose.

Karl led me into the boiler room "Room 604" where we walked around and attempted to find the incinerator. We found what we believed was the incinerator built into the building structure. Although the incinerator is still installed, it was clearly not being operated; removal would take considerable reconstruction. I feel comfortable stating this device is still installed but is non-operational thus been removed and the permit is no longer valid. I informed Karl that I would void the permit associated with the incinerator. No other permits are issued to this site and I departed at approx. 10:30am.

The notice of voidance will be sent to:

Mr. Dave Burt
GISD Director of Operations
2413 W. Maple Avenue
Flint, MI 48507-3493

The following statement will be included in the voidance letter:

Please be aware that future use of this device will trigger compliance requirements with one or more of the following federal regulations:

1. Title 40 Code of Federal Regulations Part 60, Subpart Cb—Emissions Guidelines And Compliance Times For Large Municipal Waste Combustors That Are Constructed On Or Before September 20, 1994
2. Title 40 Code of Federal Regulations Part 60, Subpart E—Standards Of Performance For Incinerators
3. Title 40 Code of Federal Regulations Part 60, Subpart BBBB—Emission Guidelines And Compliance Times For Small Municipal Waste Combustion Units Constructed On Or Before August 30, 1999
4. Title 40 Code of Federal Regulations Part 60, Subpart CCCC—Standards Of Performance For Commercial And Industrial Solid Waste Incineration Units
5. Title 40 Code of Federal Regulations Part 60, Subpart DDDD—Emissions Guidelines And Compliance Times For Commercial And Industrial Solid Waste Incineration Units
6. Title 40 Code of Federal Regulations Part 60, Subpart FFFF—Emission Guidelines And Compliance Times For Other Solid Waste Incineration Units That Commenced Construction On Or Before December 9, 2004

This report will be used to void permit 115-681 in accordance with MDEQ memo Procedure for Voiding Permits to Install, dated June 7, 1999.

NAME



DATE

4-12-16

SUPERVISOR

