

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Demo/Reno Inspection

U36160464735861

FACILITY: former residential home		SRN / ID: U361604647
LOCATION: 74 North Lincoln Ave., Iron River		DISTRICT: Upper Peninsula
CITY: Iron River		COUNTY: Iron
CONTACT:		ACTIVITY DATE: 07/26/2016
STAFF: Joe Scanlan	COMPLIANCE STATUS: Compliance	SOURCE CLASS:
SUBJECT: Unannounced inspection to determine compliance with asbestos NESHAP and applicable Michigan Air Pollution Control Rules		
RESOLVED COMPLAINTS:		

**ASBESTOS INSPECTION DATE:** 7/26/2016**DEQ-ASBESTOS NESHAP STAFF:** Joseph Scanlan**FACILITY:** Single-family residence**FACILITY OWNER:** State of Michigan**ABATEMENT CONTRACTOR:** N/A**ASBESTOS SURVEY:** Mr. Mark Breeden, AKT Peerless**DEMOLITION/RENOVATION CONTRACTOR:** Associated Constructors LLC**LOCATION:** 74 N. Lincoln Avenue, Iron River; large lot at the SE corner of Lincoln Ave & intersection; residential area**DESCRIPTION:** Abandoned dilapidated single-family home reverted to SOM as a tax foreclosure

**INSPECTION:** The facility was unsafe to enter due to lack of structural integrity of the floor joists and black mold. I did a visual survey of the exterior of the residential home and of the interior and exterior of the detached single-car garage. No suspect ACM was observable. Asbestos survey determined there was no ACM present exterior or interior of either structure.

**SUMMARY:** I did not observe any violations of the asbestos NESHAP or applicable Michigan Air Pollution Control Rules.



**Image 1(IR2)** : Exterior of residence from Lincoln St



**Image 2(IR2)** : Exterior rear of residence and small garage--facing Lincoln

NAME Joseph So

DATE 9/6/16

SUPERVISOR \_\_\_\_\_