

A7757
MANILA-FCE


DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION

FCE Summary Report

Facility : U S SILICA CO	SRN : A7757
Location : 20837 N HURON RIVER DR P. O. BOX 100	District : Detroit
	County : WAYNE
City : ROCKWOOD State: MI Zip Code : 48173	Compliance Status : Compliance
Source Class : SM OPT OUT	Staff : Todd Zynda
FCE Begin Date : 9/1/2019	FCE Completion Date : 9/1/2020
Comments :	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
09/01/2020	Scheduled Inspection	Compliance	September 1, 2020 Inspection
06/05/2020	Complaint Investigation	Non Compliance	June 5, 2020 Complaint Investigation
05/08/2020	Complaint Investigation	Non Compliance	May 8, 2020 Fallout Complaint Investigation
05/05/2020	Complaint Investigation	Non Compliance	Fallout Complaint Investigation
04/20/2020	Complaint Investigation	Non Compliance	Fallout complaint investigation
04/06/2020	Complaint Investigation	Compliance	April 6, 2020 Complaint Investigation
03/31/2020	MAERS	Compliance	MAERS REPORT SUBMITTED
03/31/2020	Other	Compliance	2019 MAERS Review

Name:  Date: 10/15/20 Supervisor: 