

GRETCHEN WHITMER GOVERNOR

## STATE OF MICHIGAN DEPARTMENT OF ENVIRONMENT, GREAT LAKES, AND ENERGY

LANSING DISTRICT OFFICE



June 14, 2021

Mr. Dan Larson, Area Manager Rieth-Riley Construction Company, Lansing 4150 South Creyts Road Lansing, Michigan 48917

SRN: B1646, Eaton County

Dear Mr. Larson:

## VIOLATION NOTICE

On May 13, 2021, the Department of Environment, Great Lakes, and Energy (EGLE), Air Quality Division (AQD), conducted an inspection of Rieth-Riley Construction Company, Lansing (Rieth-Riley) located at 4150 South Creyts Road, Lansing, Michigan. The purpose of this inspection was to determine Rieth-Riley's compliance with the requirements of the federal Clean Air Act; Part 55, Air Pollution Control, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451); the Air Pollution Control Rules; and the conditions of Permit to Install (PTI) number 97-03A.

During the inspection, staff observed the following:

| Process Description | Rule/Permit<br>Condition Violated | Comments  |
|---------------------|-----------------------------------|---|
| SV-001 Stack Height | PTI 97-03A, Condition 1.24        | Stack Height determined<br>during inspection is less<br>than the minimum<br>permitted height of 44.3<br>feet above ground level |

During the inspection, AQD staff utilized a Nikon Forestry Pro II Rangefinder to determine the stack height of SV-001. Two measurements were taken at two different locations, measuring from the base of the footing to the rim of the stack. Both measurements indicated a stack height less than the 44.3 foot minimum stack height required in PTI 97-03A, condition 1.24. The data recorded from the rangefinder were 35.9 feet and 35.6 feet. The AQD staff informed Rieth-Riley staff of this finding during the inspection.

Please initiate actions necessary to correct the cited violation and submit a written response to this Violation Notice by July 5, 2021, (which coincides with 21 calendar days from the date of this letter).

Mr. Dan Larson Rieth-Riley Construction Company Lansing Page 2 June 14, 2021

The written response should include: the dates the violation occurred; an explanation of the causes and duration of the violation; whether the violation is ongoing; a summary of the actions that have been taken and are proposed to be taken to correct the violation and the dates by which these actions will take place; and what steps are being taken to prevent a reoccurrence.

Please submit the written response to EGLE, AQD, Lansing District Office, at Constitution Hall, First Floor South, 525 West Allegan, Lansing, Michigan 48933, and submit a copy to Ms. Jenine Camilleri, Enforcement Unit Supervisor at EGLE, AQD, P.O. Box 30260, Lansing, Michigan 48909-7760. Please also submit an email copy of the written response to Michelle Luplow at luplowm1@michigan.gov.

If Rieth-Riley believes the above observations or statements are inaccurate or do not constitute violations of the applicable legal requirements cited, please provide appropriate factual information to explain your position.

Thank you for your attention to resolving the violation cited above and for the cooperation that was extended to me during my inspection of Rieth-Riley. If you have any questions regarding the violation or the actions necessary to bring this facility into compliance, please contact me at the number listed below.

Sincerely,

Michille Hours

Michelle Luplow Environmental Quality Analyst Air Quality Division 517-294-9294

cc: Mr. John Berscheit, Rieth-Riley Ms. Mary Ann Dolehanty, EGLE Dr. Eduardo Olaguer, EGLE Ms. Jenine Camilleri, EGLE Mr. Christopher Ethridge, EGLE Mr. Brad Myott, EGLE