

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection

B768526137

FACILITY: OSCEOLA REFINERY MDEQ-REMEDATION DIVISION		SRN / ID: B7685
LOCATION: 521 NORTH PARK STREET, REED CITY		DISTRICT: Cadillac
CITY: REED CITY		COUNTY: OSCEOLA
CONTACT: Nick Swiger , Environmental Engineer		ACTIVITY DATE: 07/23/2014
STAFF: Rob Dickman	COMPLIANCE STATUS: Compliance	SOURCE CLASS:
SUBJECT: Scheduled inspection of this minor source.		
RESOLVED COMPLAINTS:		

Inspected this source per General Permit number 262-09. The permitted equipment on site is used to remediate contaminated soil. There are two buildings on site which appear to house the collection equipment and two large granular activated carbon canisters used for emissions control.

This facility has not operated since November of 2012 and there are no plans for future operation. However, the permitted equipment is still on site and operable. It is recommended that permit 262-09 remain active.

NAME



DATE

7/29/14

SUPERVISOR

