

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection

B868737126

FACILITY: AMERICAN URETHANE PRODUCTS		SRN / ID: B8687
LOCATION: 4584 GRISWOLD ROAD, PORT HURON		DISTRICT: Southeast Michigan
CITY: PORT HURON		COUNTY: SAINT CLAIR
CONTACT:		ACTIVITY DATE: 10/11/2016
STAFF: Rem Pinga	COMPLIANCE STATUS: Compliance	SOURCE CLASS: Minor
SUBJECT: Unannounced Target Inspection		
RESOLVED COMPLAINTS:		

On 10/11/2016, I conducted an unannounced level 2 target inspection at American Urethane Products located in 4584 Griswold Road, Port Huron, Michigan 48060. The purpose of the inspection was to determine the facility's compliance with the requirements of the federal Clean Air Act; Part 55, Air Pollution Control, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451), the administrative rules, and the facility's Permit to Install No. 499-81.

The company manufactures urethane rod stock, sheet stock, and custom plastic molding. During office file review, I found out that the facility obtained PTI No. 499-81 for the urethane manufacturing process. I also saw a PTI Application No. 253-81 that was denied. It appeared from file review that the last AQD inspection at this facility was conducted in July 1981.

At the site, I did not observe any facility name sign and any activity outside. The address is located in a residential/commercial neighborhood but the facility itself is bounded by residential houses on both sides and across from the property. I knocked at the door but no one answers. The place appeared abandoned and I noticed a "For Sale" sign at the front lawn. I also noticed a fairly newer enclosed cargo vehicle (light duty vehicle) by the driveway that has a "For Sale" sign. The facility interior appeared dark and I could not see anything from peaking through the windows. I was not able to observe if the building is empty or still has equipment but appeared to be abandoned.

During inspection, I did not observe any air quality related noncompliance issues while at the site. I will conduct further research and a follow-up visit in the near future before totally closing this file.

NAME

DATE

SUPERVISOR