DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

Facility:	Central Michiga	ın Unive	rsity				SRN:	K2460
Location :	1720 S. East C	ampus I	Orive)			District :	Bay City
							County:	ISABELLA
City :	MOUNT PLEASANT	State:	MI	Zip Code :	48859	Comp Status	liance	Non Compliance
Source Cl	ass: MAJOR					Staf	ff: Benjaı	min Witkopp
FCE Begir	n Date : 9/4/2023					FCE Date	Completion e :	9/4/2024
Comments: CMU is working cooperatively to resolve "boiler 5" issues but remains in no- compliance status until actions take place.								

List of Partial Compliance Evaluations:

Activity Date	Activity Type	Compliance Status	Comments
09/04/2024	On-site Inspection	Non Compliance	Facility inspection
07/25/2024	CAM Excursions/Exceedan ces	Compliance	CMU sends it in to be proactive. It is only required if boiler 4 burns wood.
07/25/2024	ROP Semi 1 Cert	Compliance	Received timely. CMU maintains NSPS Db CEMS / PEMS monitoring does not apply therefore no deviations reported.
06/13/2024	Annual Emissions Report (or MAERS)	Compliance	
02/08/2024	ROP Annual Cert	Compliance	Received timely
02/08/2024	ROP SEMI 2 CERT	Compliance	Received timely
02/08/2024	CAM Excursions/Exceedan ces	Compliance	CMU sends it in to be proactive. It is only required if boiler 4 burns wood.
02/08/2024	CAM monitor downtime	Compliance	CMU sends it in to be proactive. It is only required if boiler 4 burns wood.
09/21/2023	CAM Excursions/Exceedan ces	Compliance	None reported
09/21/2023	CAM monitor downtime	Compliance	None reported
09/14/2023	ROP Semi 1 Cert	Compliance	Received timely

Name: Bliffy Date: 9-23-24 Supervisor: Date: