

M4777
FCE

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION

FCE Summary Report

Facility : BASF Corporation - Plastic Plants	SRN : M4777
Location : 1609 BIDDLE AVE.	District : Detroit
	County : WAYNE
City : WYANDOTTE State: MI Zip Code : 48192	Compliance Status : Compliance
Source Class : MAJOR	Staff : Samuel Liveson
FCE Begin Date : 7/10/2023	FCE Completion Date : 7/10/2024
Comments : Based on a facility inspection and records review, the facility appears to be in compliance with applicable rules and regulations.	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
07/10/2024	On-site Inspection	Compliance	Scheduled inspection of a Title V major source.
05/28/2024	ROP Other	Compliance	2023 ROP MAERS Certification Report Form Received
05/28/2024	ROP Annual Cert	Compliance	No deviations from ROP conditions were reported for the annual reporting period.
05/28/2024	ROP Annual Cert	Compliance	No deviations from ROP conditions were reported for the annual reporting period.
05/28/2024	ROP Annual Cert	Compliance	No deviations from ROP conditions were reported for this annual reporting period.
05/28/2024	ROP SEMI 2 CERT	Compliance	No deviations from ROP conditions were reported for this semi-annual reporting period.
05/28/2024	ROP SEMI 2 CERT	Compliance	No deviations from ROP conditions were reported for this semi-annual reporting period.
05/28/2024	ROP SEMI 2 CERT	Compliance	No deviations from ROP conditions were reported for this semi-annual reporting period.
11/17/2023	ROP Semi 1 Cert	Compliance	No deviations from Section 1 ROP conditions were reported for this semi-annual reporting period.
11/17/2023	ROP Semi 1 Cert	Compliance	No deviations from Section 2 ROP conditions were reported for this semi-annual reporting period.
11/17/2023	ROP Semi 1 Cert	Compliance	No deviations from Section 3 ROP conditions were reported for this semi-annual reporting period.

Name: *SL* Date: 10/1/24 Supervisor: *JK*
Page 1 of 1