

DEPARTMENT OF ENVIRONMENTAL QUALITY

AIR QUALITY DIVISION

FCE Summary Report

Facility : MICHIGAN METAL COATINGS	SRN : N0950
Location : 2015 DOVE STREET	District : Warren
	County : SAINT CLAIR
City : PORT HURON State: MI Zip Code : 48060	Compliance Status : Compliance
Source Class : SM OPT OUT	Staff : Robert Joseph
FCE Begin Date : 3/9/2021	FCE Completion Date : 4/27/2022
Comments : Scheduled inspection of coating facility	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
03/10/2022	On-site Inspection	Compliance	Scheduled inspection of coating facility
04/29/2021	Other Non ROP	Compliance	VOC Compliance Testing.
04/28/2021	MAERS	Compliance	MAERS Report Submission.
04/28/2021	MAERS	Compliance	MAERS Report Submission.
04/26/2021	Stack Test	Compliance	VOC Compliance testing conducted on the Plant 2 (EUDIPSPIN RTO). Destruction efficiency was 97.10% and capture efficiency was 87.64
04/20/2021	Stack Test	Compliance	Plan for the Coating Process Volatile Organic Compound Capture and Destruction Efficiency Test at Michigan Metals Facility; PTI #24-19A
03/09/2021	On-site Inspection	Compliance	Conducted a scheduled onsite inspection of Michigan Metal Coatings Company (SRN#N0950)

Name: Robert Joseph

Date: 04-27-22

Supervisor: Joyce