

DEPARTMENT OF ENVIRONMENTAL QUALITY
 AIR QUALITY DIVISION
 ACTIVITY REPORT: On-site Inspection

N115459686

FACILITY: PARKER HANNIFIN CORP		SRN / ID: N1154
LOCATION: 8676 E M 89 HWY, RICHLAND		DISTRICT: Kalamazoo
CITY: RICHLAND		COUNTY: KALAMAZOO
CONTACT: Chad Boelman , Division EHS Manager		ACTIVITY DATE: 08/18/2021
STAFF: Monica Brothers	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Unannounced, scheduled inspection		
RESOLVED COMPLAINTS:		

Staff, Monica Brothers, arrived on-site at about 2:30 pm and met with Chad Boelman, Division EHS Manager. No visible emissions were seen upon arrival. Parker Hannifin does machining and assembly of various metal and plastic parts. They have about 200 employees who work three shifts per day, Monday through Friday.

They have about five plastic injection molding machines, one parts washer, and one emergency generator. During the inspection I observed the parts washer. The SDS for the parts washer material is attached to this report. They also have a parts washer with just IPA. Both of these units had their lids closed and were also contained within an enclosure.

I also observed the Cummins 6.33 MMBTU/hr, natural gas-fired emergency generator. It usually runs for about fifteen minutes each month for readiness testing. During the inspection the unit was down for repairs, but the non-resettable hour meter read 829.9 hours. The unit is a Cummins 500 GTA unit that was manufactured and installed in 2001. It is EPA NSPS certified and is considered exempt from permitting under Rule 285(2)(g). Chad said that they do not have their hours of operation separated out by each reason the generator was run, but he said that he will track it with more detail going forward.

The facility seemed to be in compliance at the time of inspection.

NAME Monica Brothers

DATE 9/24/21

SUPERVISOR R129/22/21