

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Self Initiated Inspection

N158346164

FACILITY: Busha Motor		SRN / ID: N1583
LOCATION: 500 E HURON BLVD, MARYSVILLE		DISTRICT: Southeast Michigan
CITY: MARYSVILLE		COUNTY: SAINT CLAIR
CONTACT: James Zimmer , Owner		ACTIVITY DATE: 09/11/2018
STAFF: Adam Bogнар	COMPLIANCE STATUS: Compliance	SOURCE CLASS: Minor
SUBJECT:		
RESOLVED COMPLAINTS:		

On Tuesday, September 11, 2018, Michigan Department of Environmental Quality-Air Quality Division (MDEQ-AQD) staff, I, Adam Bogнар, conducted an unannounced self-initiated inspection of Busha Motors located at 500 East Huron, Marysville, MI 48040. The purpose of this inspection was to determine the facility's compliance status with the Federal Clean Air Act; Article II, Part 55, Air Pollution Control of Natural Resources and Environmental Protection Act, 1994 Public Act 451; Michigan Department of Environmental Quality, Air Quality Division (MDEQ-AQD) rules; and Permit to Install No. 194-87.

Permit to Install No. 194-87 was issued to "Collision Specialties" on May 13, 1987 for a "Paint 'n' Cure" Spraybooth – Model DLB-78. The facility has since changed names to Busha Motors but is under the same ownership.

I arrived at the site around 10:00 am. I met with Mr. James Zimmer. I identified myself, provided credentials, and stated the purpose of the inspection.

Mr. Zimmer gave me a tour of the facility. Busha Motors is an automotive service center that specializes in routine automobile maintenance. They are no longer a collision center. The permitted booth still exists but is seldom used. Mr. Zimmer estimates that the booth is used around once per month for relatively small touch up jobs. The booth is equipped with appropriately installed exhaust filters located in the booth floor. Booth exhaust appeared to be discharged unobstructed vertically upwards. No painting was going on during this inspection. This booth appears to comply with all conditions of Permit to Install No. 194-87.

The facility used to operate a solvent based parts washer equipped with a solvent recovery system. This has since been removed as Busha Motors no longer has any use for it. Now, when spray guns need cleaning a small spray bottle of acetone is used.

Mr. Zimmer stated that there are no boilers or emergency generators on site.

I left the facility at around 10:15 am.

Compliance Determination

Busha Motors appears to be in compliance with the requirements of the federal Clean Air Act; Part 55, Air Pollution Control, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451); Michigan Department of Environmental Quality-Air Quality Division (MDEQ-AQD) Administrative Rules; and Permit to Install No. 194-87.

NAME Adam Bogнар

DATE 9/20/2018

SUPERVISOR SK