

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection

N298447087

| | | |
|---|-------------------------------|---------------------------|
| FACILITY: C REISS COAL COMPANY / NORTH DOCK | | SRN / ID: N2984 |
| LOCATION: POWER PLANT ROAD, ESCANABA | | DISTRICT: Upper Peninsula |
| CITY: ESCANABA | | COUNTY: DELTA |
| CONTACT: Greg Schron , Manager | | ACTIVITY DATE: 11/28/2018 |
| STAFF: Sydney Bruestle | COMPLIANCE STATUS: Compliance | SOURCE CLASS: MINOR |
| SUBJECT: Onsite Inspection to Verify compliance with PTI 710-91E and all other applicable state and federal air quality regulations | | |
| RESOLVED COMPLAINTS: | | |

On November 28, 2018 I (Sydney Bruestle) performed an onsite inspection of The C. Reiss Coal Company located at 1010 3rd Avenue North in Escanaba Michigan. I met with Wade Paquin at Dock #1, Mr. Paquin was operating the weigh station. Dock #1 is located at the end of power plant road between the Escanaba Power Plant and the Escanaba Boat Launch.

PTI 710-91E is for Dock #1. EUMATERIALS covers the transfer and storage of two groups of materials. The only material at Dock #1 was a large rock salt pile (see attached pictures). There were no visible emissions at the time of my inspection. Wind was coming from the Northwest at 8 mph.

EUBARGELOADING: The company has not loaded barges from dock #1 for over a year. The diesel powered portable box hopper and stacking conveyor was not stored onsite at the time of my inspection.

EU WATERPUMP: At the time on my inspection the diesel water pump was not stored at dock one.

At the time of my inspection The C. Reiss Coal Company was in compliance with PTI 85-84E and all other applicable state and federal air quality regulations.

NAME Sydney Bruestle

DATE 12/17/18

SUPERVISOR EDJ