

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection

N361547533

FACILITY: MOBIL OIL CORP		SRN / ID: N3615
LOCATION: 4290 WALTON BLVD #03-KRD, DRAYTON PLNS		DISTRICT: Southeast Michigan
CITY: DRAYTON PLNS		COUNTY: OAKLAND
CONTACT: Adil Yaldo , Co-owner		ACTIVITY DATE: 12/18/2018
STAFF: Shamim Ahammod	COMPLIANCE STATUS: Unknown	SOURCE CLASS: MINOR
SUBJECT: Conducted a scheduled inspection of Mobil Oil Corporation (SRN: N3615. The SVE system for PTI # 840-92 is no longer on this site and this permit should be void. Hence, compliance with applicable requirements was not determined.		
RESOLVED COMPLAINTS:		

On Tuesday, December 18, 2018, at about 1:30 PM, I, Shamim Ahammod, Michigan Department of Environmental Quality-Air Quality Division (MDEQ-AQD) staff, conducted a scheduled inspection of Mobil Oil Corporation (SRN: N3615) located at 4290 Walton Boulevard, Drayton Plains, Michigan. The purpose of the inspection was to determine the company's compliance with the requirements of the federal Clean Air Act; Part 55, Air Pollution Control, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451); the Air Pollution Control Rules; and the conditions of Permit to Install Number (PTI): 840-92.

SOURCE DESCRIPTION:

MDEQ-AQD issued a PTI # 840-92 for a soil vapor extraction remediation system for Mobil Oil Corporation (facility) in 1993. The facility is currently occupied by Mobil Mart. Mr. Mark Yaldo is the owner of Mobil Mart.

INSPECTION:

At the time of inspection, I met with Mr. Brandon Yaldo, Store Cashier inside the store. I introduced myself, provided credentials and stated the purpose of the inspection. I told Mr. Brandon Yaldo that MDEQ-AQD issued a permit to install (PTI) for a soil vapor extraction and remediation system for Mobil Oil Corporation in 1993. He said he does not know anything about it and he is a new employee in this store. He contacted co-owner of Mobil Mart, Mr. Adil Yaldo for further information via phone. After the phone conversation, he let me know that they did purchase this facility in approximately 1997. Then they demolished the previous structure and rebuilt the new structure.

After speaking with Store Cashier, Mr. Brandon Yaldo, I received the contact information for the co-owner, Mr. Adil Yaldo and I left a business card and asked to have Mr. Adil Yaldo contact me. For further clarification, I contacted Mr. Adil Yaldo via phone. During the phone conversion, I told him that MDEQ-AQD issued a permit to install (PTI) for a soil vapor extraction and remediation system for Mobil Oil Corporation in 1993. He said the current facility, Mobil Mart was purchased approximately in 1997 from Mobile Oil Corporation. Then the old structure was demolished and rebuilt the new facility by PM environmental. He did not know anything about soil vapor extraction and remediation system. During my inspection, I was able to observe the entire site and no soil vapor extraction (SVE) system was observed.

Based on the onsite inspection, it is determined that the SVE system for PTI # 840-92 is no longer on this site and this permit should be void. I will send an email request to Ms. Sue Thelen, of the AQD Permit Section to void the PTI No. # 840-92. Hence, compliance with

applicable requirements was not determined

NAME

~~XXXXXXXXXX~~

DATE

01.09.19

SUPERVISOR

SK