

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Self Initiated Inspection

N371837240

FACILITY: Speedway #8752		SRN / ID: N3718
LOCATION: G5252 W. Miller Road, FLINT		DISTRICT: Lansing
CITY: FLINT		COUNTY: GENESEE
CONTACT: Ryan Sabol , Environmental		ACTIVITY DATE: 10/07/2016
STAFF: Nathaniel Hude	COMPLIANCE STATUS: Compliance	SOURCE CLASS: Minor
SUBJECT: Self Initiated inspection based on county file review and purging. Targeted due to having an older permit that generally uses temporary equipment.		
RESOLVED COMPLAINTS:		

Inspection Report**N3718- Speedway #8752 (formerly Eds Refinery Station)****G5252 W. Miller Road****Flint, MI 48507****Inspection Date:****10/7/16****Facility Contacts:**Ryan Sabol, Speedway LLC, 937-863-7667, rtsabol@speedway.comJim Innes, MDEQ RRD, 517-284-5115, innesj@michigan.gov**MDEQ AQD Personnel:**Nathan Hude – 517-284-6779, huden@michigan.gov**Facility Description:**

This site was a gas station operated as Eds Refinery until being acquired by Speedway on an unknown date. The site is now an active Speedway. No ground water / soil remediation device was found on site. The location is on the NE corner of Miller Road and S. Dye Road.

The DEQ Storage Tank Information Database websites provide the following information:

Facility ID: 00016951

LUST Site Name: Jet Gas, Flint

Leak ID: C-1277-85, Discovery Date: 9/14/1988, Substance: no info, Release Status: Open

Leak ID: C-1011-94, Discovery Date: 9/12/1994, Substance: diesel, Release Status: Open

Leak ID: C-0216-04, Discovery Date: 6/8/2004, Substance: gasoline, Release Status: Open

Owner Information: Speedway LLC, PO Box 1500, Springfield, OH 45501, Phone#: (937) 864-3000

http://www.deq.state.mi.us/sid-web/Tank_Detail.aspx?mod=lust&Site_ID=00016951

Permit Cards identifies the Company Contact as:

Mr. J Donovan Carpenter, Eds Refining Stations, PO Box 39413, Edina, MN 55439

Applicable Regulations:

PTI 210-93

Previous Inspections:

none

Previous Violations:

none

Recent Complaints (within 2 years):

none

Number of Violations Found During this Inspection:

none

Inspection Key Concerns:

none

MAERS Reporting

none

MAERS Emission Unit List

none

Inspection Summary

I stopped to inspect this site on 10/7/16. The site is an inactive Speedway gas station. I confirmed that no ground water / soil remediation device is on site after walking the property and speaking with the manager Jen Carter. She did show me a device that was recently installed behind the building. I believe it may be a building vapor intrusion device of some sort. Pictures were taken and will be attached to this report.

Due to the removal of the device, PTI 210-93 will be voided in accordance with General Condition 1.

The void notification letter will be sent to the following address:

Speedway LLC

Attn: Ryan Sabol

500 Speedway Drive

Enon, OH 45323

A copy of this report will be used to void PTI 210-93 in accordance with MDEQ memo Procedure for Voiding Permits to Install, dated June 7, 1999.

Although the permit will be voided, this site will still have an "open" status in the RRD spill database until further action by the appropriate parties is completed. The RRD contact for this site is Jim Innes.




Image 1(Sign on device) : sign



Image 2(device location) : device location

NAME *[Signature]*

DATE 10/24/16

SUPERVISOR *[Signature]*