

DEPARTMENT OF ENVIRONMENTAL QUALITY  
 AIR QUALITY DIVISION  
 ACTIVITY REPORT: Scheduled Inspection

N378534393

FACILITY: Interlochen Center for Arts		SRN / ID: N3785
LOCATION: 4000 M-137, INTERLOCHEN		DISTRICT: Cadillac
CITY: INTERLOCHEN		COUNTY: GRAND TRAVERSE
CONTACT:		ACTIVITY DATE: 03/29/2016
STAFF: Shane Nixon	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: On site inspection and records review		
RESOLVED COMPLAINTS:		

AQD staff traveled to Grand Traverse County to perform an inspection of the dry filter paint booth to determine compliance with PTI No. 991-92. No visible emissions were observed at the time of the inspection as the booth was not in operation. Paint usage records, in the form of purchase records, were available upon request and indicate the facility uses 35 gallons per year. VOC emission calculations based on material usage results in 0.1 tons per year which is less than the permit limit of 0.8 tons per year. AQD staff observed that dry filters were installed at the time of the inspection and the stack was constructed in accordance with height and diameter specifications listed in the PTI.

NAME Shane Nixon

DATE 5/2/16

SUPERVISOR 