

DEPARTMENT OF ENVIRONMENTAL QUALITY
 AIR QUALITY DIVISION
 ACTIVITY REPORT: Self Initiated Inspection

N582151104

FACILITY: HighMount - Big Bass Lake		SRN / ID: N5821
LOCATION: T29N R2W SEC 11, Otsego Co., CHESTER TWP		DISTRICT: Gaylord
CITY: CHESTER TWP		COUNTY: OTSEGO
CONTACT:		ACTIVITY DATE: 10/17/2019
STAFF: Sharon LeBlanc	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Confirmation of removal of engine/building associated with the Big Bass Lake CPF (N5821) by Riverside Energy Group.sgl		
RESOLVED COMPLAINTS:		

On Thursday October 17, 2019, AQD District Staff mobilized in an attempt to verify removal of compressor engine assigned to Big Bass Lake CPF. The most recent site inspection of the Big Bass Lake CPF was conducted on January 9, 2008. At that time the Facility was being operated by J-5.

The unit was reported as part of the Big Bass Lake-Chester Consolidation (P0928) to have been removed. Upon arrival at both the northern and southern access roads the access was found to be gated, locked, fenced, and with signs indicating camera surveillance and no trespassing. Plat maps for the area indicate that the Facility was located on apx 180 privately owned acres. District Staff determined at that time that District Oil, Gas & Minerals Staff and Riverside Staff would be contacted for verification of engine removal activities.

Discussions with Riverside Staff on October 23, 2019, confirmed that since the CPF had been removed that the property owner had kept the access closed to the public. A copy of the electronic correspondence which included photos taken by Larry Kuck, Riverside Field Foreman for the area, documenting the restored site. This information was verified by District Oil Gas & Minerals Staff on October 24, 2019.

NAME Sharon LeBlanc

DATE 10/24/2019 SUPERVISOR SN