

DEPARTMENT OF ENVIRONMENTAL QUALITY
 AIR QUALITY DIVISION
ACTIVITY REPORT: On-site Inspection

N611459649

FACILITY: BREITBURN OPERATING LP - CORWITH DOVER		SRN / ID: N6114
LOCATION: SE NE SEC 4 T31N R2W, DOVER TWP		DISTRICT: Gaylord
CITY: DOVER TWP		COUNTY: OTSEGO
CONTACT:		ACTIVITY DATE: 08/10/2021
STAFF: Becky Radulski	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: FY21 inspection		
RESOLVED COMPLAINTS:		

Traveled to N6114 Breitburn Corwith Dover CPF for an unannounced scheduled inspection to determine compliance with PTI 672-96.

The CPF is located in Dover Township, Otsego County. From Gaylord, travel north on Old-27, turn east onto Whitmarsh Rd, then south onto Peanut Hill Rd. The dirt access to the site is on the east side of Peanut Hill, the first dirt road south of Whitmarsh. Once on the dirt road, turn left at the split in the path. There is a gate at the entrance to the dirt road which was open during the inspection.

The engine was operating, no visible emissions from the exhaust stack or odors were present. A pump jack was located on the south side of the building, which was not operating.

Inside the building was a small Caterpillar engine, a small tank of engine oil and several drums. A used oil tank was located in a separate room on the east side of the main building.

Records were reviewed separately. Based on the inspection and records review, the source appears to be in compliance with the permit conditions.

NAME _____

DATE _____

SUPERVISOR _____