

DEPARTMENT OF ENVIRONMENTAL QUALITY
 AIR QUALITY DIVISION
 ACTIVITY REPORT: Scheduled Inspection

N618140771

| | | |
|--|-------------------------------|---------------------------|
| FACILITY: WARD LAKE ENERGY, CHARLTON 7 CPF | | SRN / ID: N6181 |
| LOCATION: T30N R1W SEC 7, GAYLORD | | DISTRICT: Gaylord |
| CITY: GAYLORD | | COUNTY: OTSEGO |
| CONTACT: | | ACTIVITY DATE: 07/20/2017 |
| STAFF: Bill Rogers | COMPLIANCE STATUS: Compliance | SOURCE CLASS: SM OPT OUT |
| SUBJECT: Scheduled inspection for FCE | | |
| RESOLVED COMPLAINTS: | | |

On July 20, 2017, I went to the Charlton 7 CPF to try to conduct an inspection for a Full Compliance Evaluation. I found that the facility had been removed. There was nothing left except an area of bare ground and some concrete slabs that were being used as parking space for farm equipment. There was a construction crane on site, a dumpster, and some twisted pipes that appeared to be the type used in oil and gas facilities, so it appears that the demolition of the facility may have been recent.

I am notifying Permit Section to void the permit, and marking the facility as closed, remove from the CMS inspection list.

NAME William J Rogers L. DATE 7/20/17 SUPERVISOR SN