DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

Facility: SRN: CMS Generation, Livingston Generating Station N6526 Location: 155 N. Townline Road District: Gaylord County: **OTSEGO** State: MI Zip Code: 49735 Compliance City: **GAYLORD** Compliance Status: Source Class: **MAJOR** Staff: Becky Radulski FCE Begin Date: 5/2/21 **FCE Completion** 5/2/2022 Date: Comments: FY FCE including scheduled inspection and records review

List of Partial Compliance Evaluations:

Activity Date	Activity Type	Compliance Status	Comments	
05/02/2022	On-site Inspection	Compliance	FY22 scheduled inspection and records review	
03/16/2022	MAERS	Compliance	2021 MAERS, Check MAERS for any review comments	
02/09/2022	ROP Annual Cert	Compliance	Annual Compliance pursuant to Rule 2134(4)(c)), received on time and properly certified	
02/09/2022	ROP SEMI 2 CERT	Compliance	Semi-Annual Report Cert pursuant to Rule 213(3)(c)), received on time and properly certified	
02/09/2022	CAM Excursions/Exceedan ces	Compliance	CAM Report, received on time, no reported E/E	
02/09/2022	CAM monitor downtime	Compliance	CAM Report, received on time, no reported monitor downtime.	
02/09/2022	Excess Emissions (CEM)	Compliance	EER received on time, no issues. Only reported EE were during start up/shut down.	
02/09/2022	NSPS (Part 60)	Compliance	Semi reporting for GG - no deviations reported.	
07/28/2021	ROP Semi 1 Cert	Compliance	2021 Sem1 ROP reporting January-June. No deviations reported.	
07/28/2021	CAM monitor downtime	Compliance	2021 CAM monitor downtime Sem1 ROP reporting January- June. No deviations reported.	
07/28/2021	CAM Excursions/Exceedan ces	Compliance	2021 CAM E/ESem1 ROP reporting January-June. No deviations reported.	
07/28/2021	Excess Emissions (CEM)	Compliance	Excess emissions reporting January-June. No deviations reported.	

 Part 60, GG Semi-annua reporting January-June.			
Comments	Compliance Status	Activity Type	Activity Date

Supervisor: Page 2 of 2

Page 2 of 2

Page 2 of 2