

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Self Initiated Inspection


N654135378

FACILITY: PITLIK & WICK INC #483-99		SRN / ID: N6541
LOCATION: 8075 HIGHWAY D, WATERSMEET		DISTRICT: Upper Peninsula
CITY: WATERSMEET		COUNTY: GOGEBIC
CONTACT: Glenn Stieess , Foreman		ACTIVITY DATE: 06/08/2016
STAFF: Joe Scanlan	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Unannounced inspection to determine compliance with PTI# 483-99 and applicable Michigan Air Pollution Control Rules.		
RESOLVED COMPLAINTS:		

**INSPECTION DATE:** 6/08/2016**DEQ STAFF:** Joseph Scanlan, EQA**FACILITY:** Portable Gravel Crusher**FACILITY OWNER:** Pitlik & Wick, Inc., Eagle River, WI**FACILITY CONTACT:** Carolyn Lurvey, Environmental Engineer -- [clurvey@pitlikandwick.com](mailto:clurvey@pitlikandwick.com)**LOCATION:** The crusher was moved from Wisconsin to John Kaat's Pit located off of Old M-45 in Rockland Township, Ontonagon County.

**INSPECTION:** I wore steel-toed work boots, hardhat, high-visibility DEQ vest, safety glasses, and hearing protection. I parked my work vehicle in a location that was a safe distance away from the mobile heavy equipment (loaders) that were working on site and made myself visible to one of the loader drivers, Mr. Glenn Stieess. Mr. Stieess was very cooperative and easily provided me with a copy of PTI# 483-99. Mr. Stieess said they had crushed 14,000 tons so far and would be off site in about two days. There were no fugitive dust issues that I observed and all equipment had visible identification numbers corresponding to the PTI.

**SUMMARY:** I did not observed any violations of PTI# 483-99 or any applicable Michigan Air Pollution Control Rules.



**Image 1(PW1) :** Conveyor #729



**Image 2(PW2)** : Conveyor #766




**Image 3(PW3)** : Primary Crusher #745




**Image 4(PW4)** : Secondary Crusher #737



**Image 5(PW5)** : Primary Crusher #744



**Image 6(PW6)** : Conveyor #767



**Image 7(PW7)** : Adequate water supply--no issue with spray bars



**Image 8(PW8) :** Crusher spread for PTI#483-99 at John Kaat's Pit near Rockland

NAME

*Joseph Seaton*

DATE

*7/6/16*

SUPERVISOR

*Don W. Mali*