

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION

ACTIVITY REPORT: ~~Scheduled Inspection~~ *Self Initiated*

N668440284

FACILITY: PATSY LOU WILLIAMSON BUICK GMC INC		SRN / ID: N6684
LOCATION: G-5111 CORUNNA ROAD, FLINT		DISTRICT: Lansing
CITY: FLINT		COUNTY: GENESEE
CONTACT: Joe Carrier , Service Director		ACTIVITY DATE: 06/07/2017
STAFF: Nathaniel Hude	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Follow-up inspection for possible use of "immersion cleaners" in service department.		
RESOLVED COMPLAINTS:		

Inspection Report

N6684- Patsy Lou Service Department
5111 Corunna Road, associated with 2100 S. Linden Road in MACES
Flint, MI 48532

Inspection Date:

6/7/17

Facility Contacts:

Joe Carrier, Service Director, 810-600-6543, jcarrier@patseylou.com

MDEQ AQD Personnel:

Nathan Hude – 517-284-6779, huden@michigan.gov

Facility Description:

Patsy Lou is a large GMC / Buick / Chevrolet dealership. The dealership is listed in MACES as located on 5111 Corunna Road which is accurate. Yet the collision centers (only paint shop) physical address is 2100 S. Linden Road and is co-located with the "Used Car Mega Lot". Access can be gained off from S Linden road and Health Source Boulevard. The Service Centers address is 5111 Corunna Road.

The facility is near the corner of Corunna Road and South Linden road, just south of the Health Alliance Plan (HAP) building. The area surrounding is all mixed commercial.

Applicable Regulations:

Collision Center- R336.1285 (l)(vi)(B) for grinding and sanding
Collision Center- R336.1287(1)(c) for 2 paint booths with down draft ventilation and floor filters
Service Department- R336.1707 for cold cleaners

Previous Inspections:

1/12/17- Nathan Hude, no issues

Previous Violations:

None found on record

Recent Complaints (within 2 years):

None found on record

Number of Violations Found During this Inspection:

None

Inspection Key Concerns:

none

MAERS Reporting

No, not applicable due to devices being removed

MAERS Emission Unit List

None

Inspection Summary

I arrived at approx. 1:30pm, it was sunny and I did not observe any VE's or odors when approaching the area or the building.

I checked into the office and introduced myself while asking for the manager. I was pointed towards Joe's office where I introduced myself. I informed Joe of the purpose of my visit and provided him a copy of my business card.

I explained to him that in past records, we had documented the use of four (4) Immersion Cleaners for the dealership and that I was doing a follow-up inspection after being at the collision center in January.

Joe showed me that they only had two parts washers on site; one in the oil change bay and one in the service department. The washer in the service department had its lid locked up and I took the opportunity to inform Joe on the rules for the device. The washers are serviced by Safety Kleen. Instructions were located on each cleaner's lids, but I provided Joe of a copy of our "Cold Cleaner Operating Procedures" stickers.

Joe stated that there were no immersion cleaners on the site that he was aware of. I departed the site at approx. 2:00pm.

Based on my inspection, it appears that the Patsy Lou Service Center is in compliance with state of Michigan air quality rules.

NAME



DATE

6/20/17

SUPERVISOR

