DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION ACTIVITY REPORT: Scheduled Inspection

N714050388		•
FACILITY: Savoy Energy LP		SRN / ID: N7140
LOCATION: Broomhead Rd, S BOARDMAN		DISTRICT: Cadillac
CITY: S BOARDMAN		COUNTY: GRAND TRAVERSE
CONTACT:		ACTIVITY DATE: 09/04/2019
STAFF: Caryn Owens	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Scheduled Inspecti	on	
RESOLVED COMPLAINTS:		

On Friday, August 16, 2019, Jodi Lindgren and Jeremy Howe of the Department of Environment, Great Lakes, and Energy (EGLE)-Air Quality Division (AQD) attempted to conduct a scheduled field inspection Savoy State Union F1-1 (SRN: N7140), located in the Northwest quarter of the northwest quarter of Section 1, Township 26 North, Range 9 West in Union Township, Grand Traverse County, Michigan. More specifically, the site is located approximately 1/3-mile South of North Beach Road in Union Township, Michigan. The field inspection was to determine if there was equipment still located onsite associated with the Permit to Install (PTI) 112-02.

PTI 112-02 was issued for a glycol dehydrator used to remove water from the natural gas drawn from the Niagaran formation. Based on Google Earth Images dated May 2018, it appeared all the equipment associated with the glycol dehydrator had been removed. AQD went to the site to confirm this. Based on Ms. Lindgren's and Mr. Howe's inspection, the site was vacant and was currently being logged in the area. I also talked to Mr. Mel Kiogima of EGLE Oil Gas and Minerals Division who is familiar with this area. According to Mr. Kiogima, the last of the sales occurred in August 2016, and the well was plugged and abandoned in October 2016. Therefore, based on this information, PTI 112-02 can be voided, and no further action is necessary at this time.

mens NAME

DATE

SUPERVISOR